


Churchill River, Ice Thickness Measurements - Apr 3-4, 2018



Site Number	Site Name	Longitude	Latitude	Ice Thickness (m)
N5	Below Muskrat Falls	-60.737	53.245	0.84
N6	Causeway	-60.496	53.266	0.92
N7	English Point	-60.189	53.339	0.88
N8	Goose Bay	-60.083	53.394	0.90
N9	Inflow to Lake Melville	-59.970	53.547	0.71

NOTE:

Ice thickness is not consistent it varies from place to place and changes with time. Variations in thickness and strength may be caused by a variety of factors including air temperature, snow cover, water depth, and water currents. Data users are advised to take note of this.